




# NMEA/Repeater Connection Diagram

## MASTER INSTRUMENT




## REPEATER INSTRUMENT



### IMPORTANT NOTE

All unused wires must be terminated in the connector block so that they are well insulated.



Connection required for GPS with single NMEA output

### NMEA DISPLAY (DEPTH AND LOG ONLY)

